ROOM 7417, FLAT FILES IN HTW GEOLOGY OFFICE

PHOTO # 9

ROOM 7315, PLANT SPECIMEN CABINETS

PHOTO # 10

ROOM 7025, SINGLE STACK OF MAP FILES, COE
HYDRAULICS BRANCH

PHOTO # 11



ROOM 7019, FILE STORAGE, SHELVES, AND FLAT FILES

PHOTO # 12

ROOM 7019, FILE STORAGE, SHELVES, AND FLAT FILES

PHOTO # 1

ROOM 6451, ORIGINAL CEILING SYSTEM

PHOTO # 14

ROOM 6433, MPA FILES IN U.S. FOREST SERVICE SPACE
(HAVE NOT BEEN RELOCATED AS DIRECTED)

PHOTO # 15

ROOM 5417, DEFLECTION IN FLOOR SHOWN BY GAP
AT TOP OF CABINETS

PHOTO # 16